
www.easyrefills.com.au

Genuine Canon PGI-650XL

Kit Code: K79BK

Information

neral



Printer Compatibility:

PGI-650XLBK

Cartridge Stats:

Colours: Black

5 refills per kit

CANON PIXMA MX726, MX926, iP 7260,

Ink Capacity: 22ml per chamber

Number of refills per kit:

Easyrefills manufactures all refill kits at it's

Queensland headquarters. Importing the

in most cases better than or equal to original manufacturers specifications. Each kit has a shelf life of two years and is

covered by a 100% guarantee.

finest quality American made inks that are

Copyright 2013 Easyrefills. All names and numbers used are registered trademarks of their respective owners.

www.easyrefills.com.au

MG5460, MG6360 and other printers taking

Kit Contents:

- 3 x ink bottles (Black)
- 1 x plastic gloves
- 1 x screw drill tool
- 1 x absorbent pad
- 2 x ball plugs

Preparation:

asyrefills

Ш

- Put on the gloves supplied
- Cover your work area in newspaper in case of accidental spillage.

Prepa

Ste

Ö

Fiv

6

Ste

- Read these instructions thoroughly
- Remove the cartridge from your printer (only do this when ready to refill.)

NB: Ink stains so we would recommend you wear old clothes or an apron when refilling.


S-L-O-W-L-Y and gently squeeze the ink refill

bottle to force ink into the reservoir until it is

Replace the ball plug making sure it "clicks"

firmly into place and unscrew the screw drill

tool.



Step

One

2

Step

Two

Ste

Ö

Seven

Step

Eight

Sit the cartridge in it's original plastic cradle. If you do not have the cradle simply cover the ink outlet hole with a piece of tape or your glove covered finger to prevent ink from leaking while you are refilling the cartridge.



The ball plug is located under the QR code section of the label. Note: This cartridge has two sections - a sponge filled section and an ink reservoir. The section indicated is located above the ink reservoir section on the same side as the clip.

Turn the cartridge upside down and carefully

remove the cradle or tape from the ink outlet

hole (see step 1). Note: Make sure you have

a paper towel handy as ink may have pooled

Install the cartridge into your printer and

run the head cleaning utility (see printer

before you resume printing.

manual). For best results wait 20 minutes

Ink outlet hole

during refilling and could drip.

Push the supplied screw drill tool into the ball

plug which is under the label (as indicated above) and twist a couple of times so that the screw drill tool "grabs" the ball plug. Gently lever the screw drill tool and the ball plug pops out of it's socket.



Insert the refill needle into the filling hole. Angle the needle toward the ink outlet hole at the bottom of the cartridge and push down as far as possible.

On some Canon printers you can simply

procedure when the other cartridges are

click through the error message and

warnings and the printer will continue printing. You will need to repeat this

Other Canon printers have an orange

blinking light next to the "RESUME" or

seconds to reset the printer so that it will

Both of these methods leave you without an

damage to your print head, we advise you set aside a specific day each week, fortnight

or month, depending on your print load, to

refill your cartridges whether they need it or

Phone Support

1300 730 018

not. NOTE: for best results, refill and

replace one cartridge at a time.

Ink Status Monitor. To ensure your cartridges never run dry, thereby possibly causing

print with the refilled cartridge.

"RESET" button. Hold this button for 10-15

Cartridge Empty Message?

an estimation.

out of ink.

These cartridges have chips on them which tell the computer they are empty based on

Thre

Õ

Step

Four

<u> Irouble</u>

shooting